

Good morning Michelle,

In response to your Amendment Risk Based Disposal Approval (RBDA) dated Tuesday August 12 condition 11, 2014 Rainier Commons is providing the following information:

1.
  - Blasting work continues on the west elevation of Buildings 10 and 11.
  - There have been no exceedances or breeches.
  - Blasting work is expected to continue into mid-week, next week.
  - At the commencement of blasting operations each day, Rainier Commons personnel knock on each affected tenant's door as a reminder to vacate their units during blasting hours (tenants were notified few times).
  - CGI continues to perform hand-detailing on Building 13. Areas of focus include window frames and small areas behind pipes and conduits. Paint removal is being performed utilizing approved paint stripper and hand tools. This work is expected to continue for all of next week.
  - There have been no adverse tenant interactions to report.
  - Photographs of containment structures, catch basins, and exterior elevations are taken daily. In the absence of any adverse conditions to report, these photographs will remain available for examination, but not furnished unless otherwise requested.
2. Condition 5 requires submittal to the EPA of Background levels for all indoor spaces affected by blasting. This information was provided on August 4, 2014 as part of the Attachment entitled "Daily Air Sampling and Laboratory Reports".

**Daily Particulate Monitoring Results**

<u>Date</u>	<u>Baseline TWA</u>	<u>Exterior TWA</u>	<u>Interior TWA</u>	<u>Live/Work?</u>
8/12/14	.051#	.032	.033	No
8/13/14	Non-blasting day (blasting media unavailable from Distributer)			
8/14/14	.038	.021	.044	No
8/15/14	.038	.029	.050	No

TWA = Time Weighted Average

All results are expressed in mg/m3

#A request for clarification of exceedances was submitted on August 8, 2014. No response received, to date. Note: Particulate monitoring of interior, "live/work" space will commence Monday, August 18, 2014. It is anticipated that –utilizing the current Action Level – an "exceedance" may result.

Note: Interior did not exceed Action Level. We had some maintenance done at stairs of building 10.

\*Today August 18 NVL will be taken an additional "during-work" follow-up sampling as you requested.

I will let you know once I have the analytical reports back.

Please let me know if you have any questions.

Thank you,

Vered Mizrahi  
Rainier Commons LLC

